

Regal Home Inspections, LLC

Find of the Week 5/18/2019

This happens more often than it should. A plumber cuts a beam to make life easier than routing the copper pipe over or under the beam. It seems to me that it would take longer to cut the beam than simply installing a couple of elbows in the pipe to go around it.

Beams should never be cut or drilled. At this location, there was more than one such notch in the important, structural beam.

